

Case study; cylinder change – Falmouth

The Challenge:

Trident were called out to quote for a replacement cylinder in Falmouth by



the existing hot water cylinder was causing there to be low water pressure to hot water taps and tripping the immersion heater.



The above photos show the cupboard in the house with the existing cylinder in and then the cylinder removed.

To the right are the photos of the new unvented cylinder that Trident have installed, the installation includes the registration of the cylinder with the local building authority.

Comment from Luke Sleeman – Trident Director:

Although the cupboard was built around the existing cylinder we were able to remove the shelving and remove the existing cylinder, this was carried out in one day making sure the customer was not left without water.

